



Adding orthophosphate or just adjusting pH with thick coatings likely will not minimize lead release until causes of the interfering buildups are controlled